1. Fall Outage-  No Testing on Burner Design

   Spring Outage-  Install all 48 burners



2. Fall Outage-  Conduct testing of burner design

   Spring Outage-